

HISTORIC AMERICAN ENGINEERING RECORD
INDEX TO PHOTOGRAPHS

HAER
VA
20-CLARK.V
1-

CLARKTON BRIDGE

HAER No. VA-108

(Bridge No. 6902)

Spanning the Staunton River at Virginia Route 620

Clarkton Vicinity

Charlotte County

Virginia

Photographer: Bruce A. Harms

April 1994

VA- 108-1	GENERAL VIEW IN CONTEXT, LOOKING NORTHEAST
VA- 108-2	GENERAL VIEW IN CONTEXT, LOOKING SOUTH
VA- 108-3	EAST ELEVATION, LOOKING WEST
VA- 108-4	WEST ELEVATION, LOOKING EAST
VA- 108-5	3/4 VIEW, WEST ELEVATION, LOOKING NORTHEAST
VA- 108-6	EAST ELEVATION OF THE NORTH SPAN, LOOKING NORTHWEST
VA- 108-7	PORTAL VIEW OF THE SOUTH SPAN, LOOKING NORTH
VA- 108-8	PORTAL AND DECK VIEW OF THE NORTH SPAN, LOOKING SOUTH
VA- 108-9	3/4 VIEW OF THE NORTH APPROACH, LOOKING NORTHWEST
VA- 108-10	NORTH ABUTMENT, LOOKING NORTHWEST
VA- 108-11	SOUTH ABUTMENT, LOOKING WEST
VA- 108-12	DETAIL VIEW OF STRINGER AND FLOOR BEAMS, LOOKING SOUTH TOWARD THE CENTER PIER
VA- 108-13	DETAIL VIEW OF UPPER CHORD CONNECTIONS, SOUTH SPAN, LOOKING NORTH

INDEX TO PHOTOGRAPHS
CLARKTON BRIDGE
(Bridge No. 6902)
HAER No. VA-108 (Page 2)

- VA-108-14 DETAIL VIEW OF THE LOWER CHORD CONNECTIONS, SOUTH
SPAN, LOOKING NORTH
- VA-108-15 DETAIL VIEW OF EAST END SHOE SEATED ON THE SOUTH
ABUTMENT